Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	282	(engine and ABS and (electric same steer\$5))same (controler or control)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:53
L2	8120	control near5 area near6 network	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:52
L3	6	1 and 2	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:52
L4	68178	control same area same network	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:52
L5	23	1 and 4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:52
L6	2007	(fault or fail\$5 or abnormal or malfunction)same(pannel or meter) same display\$5	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:53
L7	54	4 and 6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR ,·	ON	2007/09/17 13:04

10	1072622	(ongine or APS or (olectric near)	LIC DCDUB:	OB	ON	2007/00/17 12:54
L8	1873622	(engine or ABS or (electric near5 steer\$5))	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:54
L9	25	7 and 8	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 12:54
L10	15	("4482962" "5031089" "5313584"). PN. OR ("5796936").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/17 13:00
L11	2	2 and 6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:05
L12	470	8 and 6	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:04
L13	1	2 and 12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:05
L14	158553	network same controller	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:10

L15	120	14 and 12	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:05
L16	176006	"701"/\$.ccls. or "180"/\$.ccls. or "340"/\$.ccls. or "342"/\$.ccls.	USPAT	OR .	OFF	2007/09/17 13:06
L17	26	15 and 16	USPAT	OR	OFF	2007/09/17 13:10
L18	12241301	(network same controller)or CAN	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:10
L19	556022	(network same controller)or (CAN same controller)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:21
L20	232	6 and 19	USPAT	OR	OFF	2007/09/17 13:11
L21	78	8 and 20	USPAT	OR	OFF	2007/09/17 13:11
L22	215	(engine same stop)and (ignition same on)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:17
L23	0	21 and 22	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:16
L24	0	6 and 22	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:17

L25	90	(engine same stop)and (ignition same switch same on)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:17
L26	4896	(engine same stop)and (ignition same switch same turn\$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:17
L27	14	6 and 26	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:21
·L28	29	("5146882" "5204816" "5561332" "5725064" "5818116" "5826671" "5862497" "5875864" "5909720" "6058912").PN. OR ("6276472").URPN.	US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/17 13:21
L29	698	16 and 26	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:21
L30	158553	(network same controller)or (CAN same controller same network)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:21
L31	158553	(network same controller)or (CAN same controller same area same network)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/09/17 13:22

L32	25	29 and 31	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT;	OR	ON	2007/09/17 13:22
L33	130	("0676965" "1311542" "2244216" "3454122" "3503464" "3533484" "3623568" "3650345" "3837419" "4025860" "4042056" "4090577" "4180138").PN. OR ("4351405").URPN.	IBM_TDB US-PGPUB; USPAT; USOCR	OR	OFF	2007/09/17 13:34